Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	50	(("20030024770") or ("7117981") or ("20030111298") or ("20040256180") or ("4367255") or ("4842101") or ("4807723") or ("6886666") or ("20030062225") or ("20030221917") or ("20060225965") or ("5957242") or ("6595889") or ("6662408") or ("6758309") or ("6776263") or ("6994487") or ("20010029219") or ("20010045326") or ("20020154944") or ("20020154945") or ("20030041419") or ("20030057031") or ("20030069101") or ("20030092524") or ("20030102189") or ("20060175137") or ("20060137896") or ("20060175137") or ("4482391") or ("4946528") or ("5238537") or ("5573816") or ("5575873") or ("6241238") or ("20060070822") or ("4830179") or ("5640661") or ("270050263229") or ("4261139") or ("5643361") or ("5647905") or ("5798131") or ("6242022")).PN.	US-PGPUB; USPAT	OR	OFF	2006/12/06 14:21
L2	2	1 and (((without no "not" free lacking) near3 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:29
L3	48	1 not 2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:28
L4	18356	(428/364-396).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 14:28
L5	99	4 and (((without no "not" free lacking) near3 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:29
L6	1505	(57/223,232,231,241,250,258,295).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 14:30
L7	1430	L6 and @pd<"20010804"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L8	1307	L7 and ((without no "not" free lacking) near2 (wax)) (waxless wax\$1free)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30

			T		Tav	000040404
L9	130	L8 and (urethane poly\$1urethane)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L10	2	L8 and (elevator hoist\$3 harness\$3 tow\$3) adj (rop\$3 belt cabl\$3 line)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L11	111	L8 and (rop\$3 belt cabl\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L12	90	L11 not (L9 L10)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L13	376	(187/251).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 14:30
L14	1	L13 and (((without no "not" free lacking) near3 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:30
L15	8	L7 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:10
L16	94	5 not (L15 L14 L12 L11)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:31
L17	8	16 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free)) near4 (coat\$3 sheath\$3 film sheet layer protect\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:10
L18	340	(118/110).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 15:10
L19	3	18 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:10
L20	472	(118/110,111).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 15:10

12/6/2006 3:12:11 PM
C:\Documents and Settings\skruer\My Documents\EAST\Workspaces\Search - Elevator Belt Assy with waxless coating - 09921803.wsp

L21	4	20 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR;	OR	ON	2006/12/06 15:11
			EPO; JPO; DERWENT			
L22	116	20 and (rop\$3 belt cabl\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:11
L23	1	22 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:11
S1	2	("4624097").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/06 14:20
S2	1505	(57/223,232,231,241,250,258,295).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/05 21:34
S3	1430	S2 and @pd<"20010804"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 21:35
S4	1312	S3 and ((without no "not" free lacking) near3 (wax)) (waxless wax\$1free)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 21:49
S5	1307	S3 and ((without no "not" free lacking) near2 (wax)) (waxless wax\$1free)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 22:05
S6	130	S5 and (urethane poly\$1urethane)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 21:47
S7	2	S5 and (elevator hoist\$3 harness\$3 tow\$3) adj (rop\$3 belt cabl\$3 line)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 21:54
S8	1177	S5 not (S6 S7)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 21:54
S9	538	S5 and (rop\$3 belt cabl\$3 line)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 22:00

			•			
S10	466	S9 not (S6 S7)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 22:01
S11	111	S5 and (rop\$3 belt cabl\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 15:11
S12	90	S11 not (S6 S7)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 22:01
S13	376	(187/251).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/05 22:04
S14	1	S13 and (((without no "not" free lacking) near3 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/06 14:21
S15	8	S3 and (((without no "not" free lacking) near2 (wax)) (waxless wax\$1free))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/05 22:06